Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-0098**

Resource Identification

Property Name(s): ..... House, Route 635 {Function/Location}
Property Date: 1850
Address(s): ..... Route 635 {Current}
County/Independent City: Isle Of Wight
Vicinity of: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Exterior end	Brick	
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard

WUZIT Count:

No.	Wuzit Types	Historic?
2	Other	Historic
1	Single Dwelling	Historic
1	Corncrib	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Other
Est. Date of Construction: .... 1850 ca {VDHR Survey File} *Accessed?* .....
Primary Resource? ..... No *Number of Stories:* 0.0
Interior Plan Type: ..... *Threats to Resource:* .....
Description: Architecture Summary: Frame 19th century buildings, too overgrown to analyze. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Corncrib
Est. Date of Construction: .... 1850 ca {VDHR Survey File} *Accessed?* .....
Primary Resource? ..... No *Number of Stories:* 0.0
Interior Plan Type: ..... *Threats to Resource:* .....
Description: Architecture Summary: Frame 19th century corncrib End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Single Dwelling
Est. Date of Construction: .... 1850 ca {VDHR Survey File} *Accessed?* .....
Primary Resource? ..... Yes *Number of Stories:* 2.0
Interior Plan Type: ..... Central Passage, Single Pile *Threats to Resource:* .....
Description: Architecture Summary: Simple window trim, unbeaded weatherboards, sawn plaster lath. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: I-house End Interior Description

Cemetery Information

Bridge Information

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0098**

ational Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Significance Statement: 19th century farmstead with many of its early components. However, l much decayed.

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos			0 /99/99	

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Reconnaissance Survey
Date: .... 1990/7 /4
Organization or Person: ..... Willie Graham
CRM Event Notes or Comments: .....

VIRGINIA
DIVISION OF HISTORIC LANDMARKS
HISTORIC DISTRICT/BRIEF SURVEY FORM

File no. 46-98
Negative no(s).

City/Town/Village/Hamlet: Windsor Vicinity — County: Isle of Wight
Street address or route number: Rte. 635, .5 mi. east of Rte. 610 — U.S.G.S. Quad: Windsor
Historic name: — Common name:


Present use: Abandoned — Building Style: Vernacular
Original use: Farmstead — Building Date(s): 2nd half of 19th century

1. Construction Materials

- ☒ wood frame
- ☐ brick
  - bond: ☐ English ☐ Flemish ☐ ____-course American ☐ stretcher ☐ other ____
- ☐ stone
  - ☐ random rubble
  - ☐ coursed rubble
  - ☐ ashlar ☐ dressed ☐ rock-faced
- ☐ log:
  - ☐ squared ☐ unsquared
  - notching: ☐ V-notch ☐ saddle ☐ square ☐ half dovetail ☐ full dovetail ☐ diamond
- ☐ concrete block
- ☐ terra cotta
- ☐ steel frame
- ☐ other ____

2. Cladding Material

- ☒ weatherboard
- ☐ vertical siding
- ☐ board & batten
- ☐ shingle: ☐ wood ☐ asbestos ☐ asphalt
- ☐ bricktex
- ☐ other ____
- ☐ composition siding
- ☐ stucco
- ☐ aluminum or vinyl siding
- ☐ cast iron
- ☐ sheet metal
- ☐ enameled metal
- ☐ glass



3. Stories (number): 2
- ☐ low basement
- ☐ raised basement

4. Bays (number): front 3 side (church) ____
- ☐ symmetrical
- ☐ asymmetrical

5. Roof Type
- ☐ shed ☐ parapet?
- ☒ gable ☐ pediment? ☐ parapet? ☐ clipped end? ☐ cross gable? ☐ central front gable?
- ☐ hipped ☐ pyramidal?
- ☐ mansard
- ☐ false mansard
- ☐ gambrel
- ☐ flat ☐ parapet?
- ☐ roof not visible
- ☐ other ____

6. Roofing Material
- ☐ shingle
  - ☐ composition (asphalt, asbestos, etc.)
  - ☐ wood
- ☒ metal
  - ☒ standing seam
  - ☐ corrugated
  - ☐ pressed tin (simulated shingles)
- ☐ tile ☐ pantile ☐ flat ☐ glazed
- ☐ slate
- ☐ not visible

7. Dormers (number): front ____ side ____
- ☐ gable ☐ pediment?
- ☐ shed
- ☐ hipped

8. Primary Porch
- style ____
- stories ____
- levels ____ bays ____
- materials ____
- description and decorative details ____

9. General supplementary description and decoration: Simple window trim, unbeaded weatherboards, sawn plaster lath. House in ruins.

10. Major additions and alterations:

11. Outbuildings: 3 frame 19th-century buildings, one of which served as a corn crib. Others too overgrown to analyze.

12. Landscape Features:

13. Significance: 19th-C farmstead with many of its early components. However, much decayed.

Surveyed by: Willie Graham — Date: 7/4/90

CONTINUATION:

Dwelling - Rte. 635, .5 mi. eas
Rte. 610






FIGURE 9
Architectural Resources Identified During Survey